CERTIFICATE OF REGISTRATION

認証登録証明書

ヨネックス株式会社 新潟工場

新潟工場第二：新潟県長岡市塚野山 900-1

事業所名及びその所在地は添付付属書参照

貴組織のマネジメントシステムが以下の規格に適合していることを確認しました。

ISO 9001:2015

本マネジメントシステムは下記の認証登録範囲に適用されます。

テニス及びバドミントンラケット、ゴルフクラブ、スノーボード
及びロードバイクフレームの設計、開発及び製造

COPY

認証登録番号:
03418

初回登録日:
2006 年 7 月 18 日

認証決定日:
2025 年 8 月 19 日

認証発行日:
2025 年 8 月 19 日

有効期限:
2028 年 9 月 27 日

Rathin Grover
President, Business Assurance

Intertek Certification Limited, 10A Victory Park, Victory Road, Derby DE24 8ZF, United Kingdom

Intertek Certification Limited is a UKAS accredited body under schedule of accreditation no. 0014.
In the issuance of this certificate, Intertek assumes no liability to any party other than to the Client, and then only in accordance with the agreed upon Certification Agreement. This certificate's validity is subject to the organization maintaining their system in accordance with Intertek's requirements for systems certification. Validity may be confirmed via email at certificate.validation@intertek.com or by scanning the code to the right with a smartphone. The certificate remains the property of Intertek, to whom it must be returned upon request.

CERTIFICATE OF REGISTRATION

APPENDIX

この認証登録証明書で網羅する各事業所の名称及び所在地

ヨネックス株式会社 新潟工場

この付属書は認証登録証明書# 03418 本体に付属するものであり、単独での使用はできません。

ヨネックス株式会社 新潟工場第二

新潟県長岡市塚野山 900-1

ヨネックス株式会社 新潟工場新産

新潟県長岡市新産 3-7

ヨネックス株式会社 新潟工場第三

新潟県長岡市塚野山 2870-1

ヨネックス株式会社 新潟工場長岡

新潟県長岡市高頭町中山 469-2

【認証登録範囲】テニス及びバドミントンラケット、ゴルフクラブ、スノーボード
及びロードバイクフレーム設計、開発及び製造

COPY

Intertek Certification Limited is a UKAS accredited body under schedule of accreditation no. 0014.
In the issuance of this certificate, Intertek assumes no liability to any party other than to the Client, and then only in accordance with the agreed upon Certification Agreement. This certificate's validity is subject to the organization maintaining their system in accordance with Intertek's requirements for systems certification. Validity may be confirmed via email at certificate.validation@intertek.com or by scanning the code to the right with a smartphone. The certificate remains the property of Intertek, to whom it must be returned upon request.